

Updating Software when Verification Key is Out of Date

- 1) [SSH](#) into the Pocket NC
- 2) Run the following command:

```
bash <(curl -k https://ostree.pocketnc.com/import\_gpg.sh)
```